

Informacje dotyczące bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC)

INFORMACJE ZWIĄZANE Z ART. 33 ROZPORZĄDZENIA REACH ORAZ SUBSTANCJAMI STANOWIĄCYMI BARDZO DUŻE ZAGROŻENIE

Szanowny Kliencie,

Art. 33(1) Rozporządzenia REACH (Rozporządzenie WE nr 1907/2006) ma na celu umożliwić klientom dostarczanych produktów zarządzanie potencjalnym ryzykiem związanym z faktem, iż pewne artykuły zawierają substancje stanowiące bardzo duże zagrożenie (SVHC) wymienione na bieżącej liście kandydackiej substancji stanowiących bardzo duże zagrożenie, oczekujących na pozwolenie, czego celem jest zagwarantowanie bezpiecznego korzystania z tych artykułów.

FORD popiera cele Regulacji REACH, w tym również Art. 33(1), które są zbieżne z naszymi dążeniami do promocji produkcji, obsługi oraz użytkowania produktów w sposób odpowiedzialny.

Identyfikacja substancji SVHC

Według naszej najlepszej wiedzy wynikającej z informacji pochodzących z naszego łańcucha dostaw oraz posiadanych danych produktowych, substancje SVHC obecne w elementach komponentów w stężeniu przekraczającym 0,1% wag. zostały wskazane dla określonego pojazdu/części na stosownej „Liście substancji stanowiących bardzo duże zagrożenie (SVHC)”.

Szczegółowe informacje dotyczące bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC)

W odpowiednich przypadkach, stosowna „Lista substancji stanowiących bardzo duże zagrożenie (SVHC)” obejmuje szczegółowe informacje dotyczące bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC), przypisane określonemu pojazdowi/części.

Ogólne informacje dotyczące bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC)

Każdy pojazd marki FORD zawiera instrukcję użytkowania, która obejmuje informacje dotyczące bezpiecznej eksploatacji skierowaną do właściciela/kierowcy pojazdu. Informacje marki FORD dotyczące napraw oraz serwisowania pojazdów, a także oryginalnych części również obejmują informacje o bezpiecznej eksploatacji dla personelu serwisowego.

W razie obecności substancji SVHC w częściach tego pojazdu, substancje SVHC wymienione na stosownej „Liście substancji stanowiących bardzo duże zagrożenie (SVHC)” dla danego pojazdu/części zostały wykorzystane w sposób

minimalizujący potencjalny kontakt klienta z substancją, wykluczając zagrożenie dla ludzi oraz środowiska pod warunkiem, że pojazd oraz jego części są eksploatowane zgodnie z przeznaczeniem, a wszelkie naprawy, usługi serwisowe oraz czynności konserwacyjne są realizowane zgodnie z instrukcjami technicznymi dotyczącymi tych czynności, a także wszelkimi dobrymi praktykami branży.

Zgodnie z przepisami obowiązującymi na terenie Unii Europejskiej, utylizację zużytego pojazdu można przeprowadzić wyłącznie w autoryzowanym punkcie złomowania. Części pojazdu należy utylizować zgodnie z obowiązującymi w danym regionie przepisami i lokalnymi wytycznymi.

Model: Ford Bronco Sport

Lista substancji stanowiących bardzo duże zagrożenie (SVHC) opracowana w oparciu o Listę kandydacką substancji stanowiących bardzo duże zagrożenie, oczekujących na pozwolenie, opracowaną przez agencję ECHA (ostatnia aktualizacja: 1 stycznia 2026 r.)

Szczegółowe informacje dotyczące bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC)

Przedstawienie szczegółowych informacji dotyczących bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC) nie jest wymagane – należy postępować zgodnie z Ogólnymi informacjami dotyczącymi bezpiecznego korzystania z artykułów zawierających substancje stanowiące bardzo duże zagrożenie (SVHC).

Commodity	REACH SVHCs
Accessories	1,2-Dimethoxyethane [110-71-4] 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] Di-(2-ethylhexyl)phthalat [117-81-7] Lead [7439-92-1] Triphenyl-phosphate [115-86-6]
Air Induction	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1] Bumetrizole [3896-11-5] Lead [7439-92-1]
AIS - Air Cleaner and Low Pressure Ducts	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Appliques (Pillar, Decklid, Roof)	Lead [7439-92-1]
Auto Transmission	Lead [7439-92-1]
Auto Transmission Cooler and Lines	Lead [7439-92-1]
Auto Transmission Shifter	Lead [7439-92-1]
Body and Security Electronics	Lead [7439-92-1]

	Octamethylcyclotetrasiloxane [556-67-2]
Body Covers and Ornamentation	C,C'-azodi(formamide) [123-77-3]
Body Structure - Decklid/Liftgate (incl Hinge/Supt)	Dicyclohexyl-phthalate [84-61-7]
Brakes	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
Bumpers and Spoilers	Di-(2-ethylhexyl)phthalat [117-81-7]
CCB (IP cross car beam)	Lead [7439-92-1]
Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	Melamine [108-78-1]
Closures and Lids Mechanisms	Boric acid [10043-35-3]
	Lead [7439-92-1]
Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Dressed Engine	Lead [7439-92-1]
Driveline	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Boric acid [10043-35-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
Driveline (Powerpack)	Lead [7439-92-1]
Driver Controls	Lead [7439-92-1]
Dynamic Sealing	Imidazolidine-2-thione [96-45-7]
EDS	Cobalt sulphate [10124-43-3]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Exhaust Cold End	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
Front / Rear Door Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Ethoxyethanol [110-80-5]
Fuel	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
GOR and Radiator Support	Lead [7439-92-1]
Headliner / Sunvisor	Lead [7439-92-1]
IP and Console	Bumetrizole [3896-11-5]
IP Substrate and Ducts	Bumetrizole [3896-11-5]

Lower Body Structure	Dicyclohexyl-phthalate [84-61-7]
Mirrors	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Cyclohexane-1,2-dicarboxylic anhydride [85-42-7]
	Lead [7439-92-1]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Octamethyltrisiloxane [107-51-7]
	TBBA [79-94-7]
Power Supply	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	1-Methyl-2-pyrrolidone [872-50-4]
	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
	TBBA [79-94-7]
Roof	Lead [7439-92-1]
Safety Electronics	Lead [7439-92-1]
Seat Belts (Front and Rear)	Lead [7439-92-1]
Seating	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Melamine [108-78-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Sodium borate, decahydrate [1303-96-4]
Seats - Foam - Cut and Sew	Melamine [108-78-1]
Seats - JIT	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Seats - Structures	Lead [7439-92-1]
Shock Absorbers	Lead [7439-92-1]
Side Door Mechanisms	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	TBBA [79-94-7]
Side Doors BIW	Cobalt sulphate [10124-43-3]
Steering	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Suspension Frames and Mountings	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methylimidazole [693-98-1]
	Lead [7439-92-1]
	Melamine [108-78-1]

Upper Body Structure	Dicyclohexyl-phthalate [84-61-7]
Wash-Wipe	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Wiper Assembly (Rear, Front) & Washer System	Lead [7439-92-1]